



Datasheet



0370 330 6021

www.sunbeltrentals.co.uk



PW41i

Universal Test System

Specifications

Voltage generators

Setting range	
3-phase ac (L-N)	3×0...300V
1-phase ac (L-L)	1×0...600V
dc (L-L)	1×0...600V
Power	
3-phase ac (L-N)	3×85VA at 300V
1-phase ac (L-L)	1×170VA at 600V (two generators in series)
dc (L-N)	3×80W at ±300V
Accuracy	
	<0.16% rd.+0.04% rg. guar., <0.08% rd.+0.02% rg. typ.,
Ranges	
	300V
Resolution	
	10mV
Distortion	
	0.1%

Current generators

Setting range	
3-phase AC(L-N)	3×40A
1-phase AC(L-N)	1×120A
dc (L-N)	3×10A
Power	
3-phase AC(L-N)	3×65VA at 5A
1-phase AC(L-N)	3×400VA at 40A
dc (L-N)	90W at 10A
Accuracy	
	<0.16 rd.+0.04% rg. guar., at 0~30A <0.08 rd.+0.02% rg. typ., at 0~30A
Distortion	
	0.1%
Resolution	
	5mA (1mA, low grade)

General

Frequency	
Range	DC, 1 to 1000Hz
Accuracy	0.002%
Resolution	0.001 Hz
Phase	
Angle range	0...360°
Accuracy	0.2°
Resolution	0.001°

Auxiliary dc supply

Voltage range	0V, 220V, 110V
Power	110W at 220V, 55W at 110V

Binary inputs

Number	8
Input characteristics	Dry/Wet
Max. measuring time	999999.999 s
Accuracy	1ms±0.1%
Resolution	1ms

Binary output, relay

Number	4
Type	Potential free relay contacts, software controlled
Break capacity ac	Vmax: 300Vac /Imax: 1A /Pmax: 125VA
Break capacity dc	Vmax: 300Vdc /Imax: 1A /Pmax: 60W

Power supply

Nominal input voltage	110~240Vac
Permissible input voltage	90~260Vac
Nominal frequency	50/60Hz
Permissible frequency	45~65Hz

Environmental conditions

Operation temperature	0...+50°C
Storage temperature	-25...+70°C
Relative humidity	5...95% non - condensing
EMC (Emission)	IEC-61000-3-2/3
EMC (Immunity)	IEC 61000-4-2/3/4/5/6/11
Safety	IEC 61010-1

Others

2 USB Ports	USB-Disk, Mouse, Keyboard
Ground Socket (earth)	4 mm banana socket; front side
Weight	18kg
Dimensions (W x H x D)	364mm × 200mm × 475 mm



PONOVO POWER CO., LTD.

2F, 4Cell, Tower C, In.Do Mansion, No.48A Zhichun Road, Haidian District Beijing, PR China (100098)
Tel. +86 (10) 8275 5151 (reception) Tel. +86 (10) 82755151 ext.8887
Fax. +86 (10) 8275 5151-8103 support@relaytest.com info@relaytest.com www.relaytest.com

We are supporting you to deliver
a world class service, every day,
in every sector...

LOCATIONS

LONDON, HEATHROW

Sunbelt Rentals UK Test & Monitoring

242-252 London Road, Staines, London TW18 4JQ

0333 122 3126

www.sunbeltrentals.co.uk/find-a-depot/london-heathrow

REDCAR

Sunbelt Rentals UK Test & Monitoring

Unit 5 Kirkleatham Business Park, Redcar TS10 5SQ

0370 330 6021

www.sunbeltrentals.co.uk/find-a-depot/teesside

STOKESLEY

Sunbelt Rentals UK Test & Monitoring

2 Ellerbeck Way, Stokesley Business Park, Stokesley, North Yorkshire TS9 5JZ

01642 718 900

www.sunbeltrentals.co.uk/find-a-depot/stokesley



www.inlec.com

Order Online with Next Day
Delivery, Online Chat & Online
Account Management



★ Trustpilot

View our trustpilot score



STOKESLEY  REDCAR

 HEATHROW

0370 330 6021

instrumentation@sunbeltrentals.co.uk

testequipment@sunbeltrentals.co.uk

www.sunbeltrentals.co.uk

